

MONUMENT RECORD
State of Indiana - County of Monroe

Section: 21

Township: 7 North



Range: 1 East

Corner ID: Polk M-17

Monument Description & Remarks: 3" Brass Disk on aluminum pipe found. Survey Sign 3ft above ground at Pt. (B). Stone, with "+" found next to monument.

References On File: Edmund O. Farkas survey, VannieMyers Est., on file in surveyors office.

RECOVERY TIE DRAWING
Field Book 33 Page No. 13




- A - 3" Brass Disk on aluminum pipe.
- B - N 67° W 3.58' to PK nail
in 12" Black Walnut.
- C - N 53° E 5.25' to PK nail
in 17" Yellow Poplar.
- D - S 36° E 27.25' to PK nail
in 15" Chinquapin Oak.

Not To Scale
Compass Bearing Magnetic North



I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of Sections 2-11 of the Indiana Code; and the above data is given under my hand and seal this 2nd day of August, 2000.





Administered by the Monroe County Surveyor

Date: See SRB minutes 7-18-06 DB

CORNER I.D. #

POLK


M - 17

MONUMENT RECORD

STATE OF INDIANA ~ COUNTY OF MONROE

SECTION 22, TOWNSHIP 7 NORTH, RANGE 1 EAST

MONUMENT DESCRIPTION & REMARKS: BRASS MONUMENT MARKING THE SOUTHWEST CORNER OF SECTION 22.



STATE OF INDIANA

COUNTY OF MONROE

I, STEVEN V. FARKAS, HEREBY CERTIFY THAT THIS DOCUMENT WAS PREPARED UNDER MY DIRECTION IN ACCORDANCE WITH THE PROVISIONS OF SECTION 17-3-64-4 THROUGH 17-3-64-8 OF THE INDIANA CODE, BEING ACTS OF 1965, CHAPTER 319; AND THE ABOVE DATA IS GIVEN UNDER MY HAND AND SEAL
THIS _____ DAY OF _____, 200__ A.D.

INDIANA REGISTERED LAND SURVEYOR No. _____ OR

UNITED STATES GOVERNMENT AGENCY

TITLE

FIELD BOOK: _____

PAGE: _____

DRAFT #: 110

Polk-M17

CERTIFIED LAND CORNER RESTORATION

State of Indiana

County of Monroe

SS.

I Andrew J. Sobiech, do hereby certify that on the 13 day of May, 1974, I found evidence of the Section corner of Sec. 21, 22, 27, 28 Township 7 North, Range 1 East, Second Principal Meridian, as described hereon; and that from this evidence I established a new monument to perpetuate the original location of this corner:

Description of original monument and accessories and

Original monument was a wood post set in 1814.

Original witnesses:

Chestnut	Poplar
20" Di.	6" Di.
S 18° E	S 7° W
4 lks	27 lks

Stone location incorrect
set new pipe
Need new certificate


Description of corner evidence found:

Found a sandstone 4"x4" marked with + on top. The stone is at the north edge of an old road bed, and near the intersection of fences from north, south, east and west.

Description of monument and accessories I established to perpetuate the original location of this corner:

I left the stone in place and made following new witnesses:

Poplar	4"x4" Post	Elm	Sassafras
4" DBH	S 24° W	8" DBH	11" DBH
S 64° W	19.4 feet	S 14° E	S 60° E
9.0 feet		30.5 feet	13.2 feet



Field Assistant

Resident witnesses

Henry Deaton - U. S. Forest Service

Dated at Brownstown Indiana, this 7 day of May, 1975.

Signature Andrew J. Sobiech Title R.L.S.
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Surveyors Registration No. S-0143

Office of _____ County of _____
I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____, and was filed in Book No. _____ Page No. _____ of County Records.

Signature _____ Title _____

Township 7 North, Range 1 East, Section 21, 22, 27, 28, Index No. R-13, Page No. _____

Index No. R-13
(Alphabetical - Numerical)


LAND CORNER RECORD
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)
GPO 806-924

T. 7N R. 1E Mer. N.F. Hoosier County Monroe State Ind.
Section 21, 22, 27 and 28
Corner common to sections

EXISTING SURVEYS

Original Government Survey	Original Evidence Found
Year surveyed <u>1973</u>	Year of search <u>1973</u> By <u>H. Denton</u>
Original monument <u>wood post</u> (Wood post, stone, pile of stones, pipe, etc.)	Monument found
Bearing Trees	Original Bearing Trees Found
Species <u>chestnut</u>	Species
Diameter <u>20"</u>	Diameter
Bearing <u>S 8 E</u>	Bearing
Distance <u>27</u>	Distance
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration Found
Year surveyed _____ By _____	Year of search <u>1973</u> By <u>H. Denton M. Briner</u>
Where filed or recorded _____	Found <u>stone</u>
Monument _____ (Original, concrete post, iron rod, etc.)	
Bearing Trees, Reference Objects	Bearing Trees, Reference Objects
Species _____	
Diameter _____	
Bearing _____	
Distance _____	



Sketch

○ Corner ☒ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
Object _____
Record distance _____
Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc. Cite source of testimony if any. Found 52nd stone 4"x4"x1' marked with + on top. Stone was put right in ground.
Found second stone 1' W of 1st stone. mark on side S 23° R 1 E lying on ground.
Both stones are at intersection of NS-EW Fences and on North bank of old road bed

Perpetuation Record

Monument and accessories established. Include brief description of area. leave stone make new witnesses

Certified corner restoration certificate prepared: Yes _____ No _____
Filed in county records at _____ Date _____ County Document No. _____
Identified on aerial photo No. _____ Which is filed at _____

At time of search:
1. Did you have the record description?
Yes _____ No _____

2. How was search area located?
Pacing, chaining, photos, maps, etc. _____

3. Man hours spent in search _____

4. Do you think additional search might recover evidence? Yes _____ No _____

5. Signature _____

LAND CORNER RECORD

5680-2

1. T 7N R 1E No. _____ Cor. _____ Mer. 24 State Indiana N.F. Hoosier Dist. B'ham

2. Corner Status



3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners:

sandstone lying flat 9" above ground

5. Investigation Notes:

*Remonumented with steel pipe
either by county or Corp of Engineers*

1-1-67

J. Haulry

7. Photo Identification

Photo No. _____

Ident. By: _____

8. Plane Coordinate Position Data

State _____ Zone _____

X _____

Y _____

Estab. By _____

Field Book No. _____

Where Filed _____

9. Evaluation

Authentic _____

Needs Verif. _____ Monument _____

Re-estab. _____ Survey _____

Land Status _____

6. Signed _____ Title _____ Date _____

PERPETUATION RECORD

10. Monument:

11. Accessories

12. Set By _____ Title _____

License _____ Agency _____ Date _____

13. Recorded By _____ Field Book _____ Page _____

(Agency) Volume _____ Page _____

(Date) (City) (County) (State)

14. Remarks: